

CASE STUDY: K-Redi-Liner®

Product: K-Redi-Liner® Ceramic Modular Lining

Product category: System Flow & Anti Wear

Location: Leslie Vale Quarry, Tasmania

Conveyed material: Crushed dolerite, 60 mm

Existing wear liner installed: Hardox 500 steel wear liner 9kg

250 tonnes per hour

Installation date: February 2010

Date of first service inspection: May 2011

Previous problem:

Rate:

Leslie Vale Quarry produces more than 700,000 tonnes a year of highquality hard rock dolerite products, supplying the construction industry with high-quality aggregate in road base materials.

In addition to their fixed plants, at Leslie Vale they operate a modern fleet of track-mounted mobile crushing and screening plants, comprising primary, secondary and tertiary units, screens and pugmills. The plant can be configured to suit many applications with crushing and screening units having a production capacity of up to 250 tonnes an hour.

A consequence of the volume of their crushing operations was the high frequency of replacement of the existing steel wear liner, lasting on average only 5 months.

"Kinder Australia suggested I trial the K-Redi-Liner® Ceramic panels because of their superior wear properties. I was getting very frustrated with the inadequate performance of the Hardox product for our Quarry's needs"



https://kinder.com.au

Kinder Australia Pty Ltd

26 Canterbury Road, Braeside VIC 3195 PO Box 1026, Braeside VIC 3195

≅ +61 3 8587 9111 **≘** +61 3 8587 9101

↑ conveyorsolutions@kinder.com.au ABN: 28 006 489 238






CASE STUDY: K-Redi-Liner®

Resolution:

"Your follow-up phone call has come just at the right time because I need to re-order a new panel. The K-Redi Liner® Ceramic Lining System has lasted for over 3 years. It is so much better than the Hardox panels that I used previously, and has far exceeded my expectations.

I can get on with my job because it's one less product I need to shop around for. I know I can rely on Kinder's K-Redi Liner.®"



3D drawing of K-Redi-Liner® Ceramic



Photo taken on site at Leslie Vale Quarry 15 months after installation.



https://kinder.com.au

Subject to © Kinder Australia Pty Ltd Issue: 202102

Kinder Australia Pty Ltd

26 Canterbury Road, Braeside VIC 3195 PO Box 1026, Braeside VIC 3195

☎ +61 3 8587 9111 **골** +61 3 8587 9101

↑ conveyorsolutions@kinder.com.au ABN: 28 006 489 238

