

Case Study - K-Spiromax® Cleaning and Tracking Roller

Product: K-Spiromax® Cleaning and Tracking Roller

Product category: Belt Cleaning Idlers

Location: South-East Victoria

Conveyed materials: Granite 30mm minus

Conveyed belt width: 1200mm

Rate: 350 tonnes per hour

Installation Date: September 2011

Previous problem:



Based in South-East Victoria, our customer's core activity is the extraction and provision of granite based aggregates. In the winter months when conditions become wet with the usual seasonal weather, the quarried material was not effectively being scraped off the return belt by the existing primary and secondary belt cleaners.

The problem was significant because as the clogged sticky material passed through both the primary and secondary cleaners, these conventional rigid blade cleaners were working twice as hard and wearing prematurely. The bumpy movement of the excess wet residue created too much contact with the cleaner blades and they were causing damage to the belt also.



Right: Typical return roller clogged with wet conveyed material, creating a build up of spillage, and long term potential to damage the belt itself.



https://kinder.com.au

Subject to © Kinder Australia Pty Ltd Issue: 202102

Kinder Australia Pty Ltd

26 Canterbury Road, Braeside VIC 3195 PO Box 1026, Braeside VIC 3195

≅ +61 3 8587 9111 **≘** +61 3 8587 9101

⊕ conveyorsolutions@kinder.com.au ABN: 28 006 489 238





Case Study - K-Spiromax® Cleaning and Tracking Roller

Resolution:

K-Spiromax® Cleaning and Tracking Roller – Key Features

- Suitable for all belt widths
- Uses standard return brackets
- Suitable for reversing belts
- Not effected by mechanical fasteners

Because the Quarry Manager had used **K-Spiromax® Cleaning and Tracking Rollers** at a previous site, he already had experienced the benefits of this wear resistant polyurethane cleaning idler. So he did not hesitate in ordering it again.

The K-Spiromax® Cleaning and Tracking Roller offers a low maintenance solution to belt cleaning, with sticky carry back cleaned off easily by the belt friendly polyurethane spirals. **It can be used in both dry and wet applications**. Ideally it is positioned over the discharge chute or a collection hopper so that the excess conveyed material can be cleared away simply, requiring no extra labour.

This cleaning idler has now been in production at this site for 4 years and is showing no signs of wear. It has reliably dealt effectively with the clogged material on the return belt, providing extra back-up cleaning during periods of wet weather. In the drier months, the K-Spiromax® Cleaning and Tracking Roller stays in place, acting as a standard idler on the return belt.



Right: K-Spiromax® Cleaning and Tracking Roller installed on the return belt.



https://kinder.com.au

Subject to © Kinder Australia Pty Ltd Issue: 202102

Kinder Australia Pty Ltd

26 Canterbury Road, Braeside VIC 3195 PO Box 1026, Braeside VIC 3195

≅ +61 3 8587 9111 **≘** +61 3 8587 9101

↑ conveyorsolutions@kinder.com.au ABN: 28 006 489 238

